

## Mazak QT10 Parameter List

										X	Z
B10	0	0	P1	12	P17	155	P33	0	PX1	1969	1969
B11	95	4	P2	20	P18	1255	P34	0	PX2	0	0
B12	93	27	P3	20	P19	100	P35	3937	PX3	197	197
B13	93	32	P4	0	P20	0	P36	3937	PX4	0	0
B14	95	50	P5	0	P21	0	P37	0	PX5	0	0
B15	105	15	P6	0	P22	0	P38	0	PX6	0	0
B16	45	45	P7	0	P23	16	P39	0	PX7	0	0
B17	60	60	P8	3	P24	787	P40	500	PX8	0	0
B18	63	62	P9	0	P25	79	P41	180000	PX9	0	0
B19	75	15	P10	0	P26	1969	P42	3937	PX10	0	0
LK1	0	0	P11	0	P27	197	P43	0	PX11	0	0
LK2	0	0	P12	0	P28	394	P44	0	PX12	0	0
LK3	0	0	P13	0	P29	394	P45	0	PX13	0	0
LK4	0	0	P14	1	P30	0	P46	0	PX14	0	0
LK5	0	0	P15	0	P31	25	P47	1969	PX15	0	0
LK6	0	0	P16	1	P32	2000	P48	1969	PX16	0	0

										X	Z
BL	255	20	TCC	10	SD1	2	T1	10	OP1	0100	0011
ZP	1023	364	CH	5	SD2	2	T2	30	OP2	1111	1111
DF	120	120	ED	4	SD3	0	T3	5	OP3	0000	0000
ZR	0	0	OT	1	SD4	0	T4	20	OP4	1111	1111
RF	10000	10000	SQ	19993	SD5	0	T5	60	OP5	0000	0000
TC	120	120	THC	0	SD6	0	T6	20	OP6	1111	1011
MC	312	011	TPM	100	SD7	0	T7	5	OP7	0000	0101
OD	0	0	GR1	1210	SD8	0	T8	5	OP8	1111	0111
LP	33	33	GR2	3000	QD1	1	T9	30	OP9	0000	0010
GS	0	0	GR3	0	QD2	41	T10	3	OP10	1111	1101
A1	0	0	GR4	0	QD3	41	T11	3	OP11	0000	0000
A2	0	0	SML	0	QD4	0	T12	180	OP12	1111	1111
A3	0	0	SMM	0	QD5	0	T13	0	OP13	0000	0000
A4	0	0	SMH	0	QD6	0	T14	0	OP14	1111	1111
A5	0	0	A6	0	QD7	0	T15	3	OP15	0000	0000
RP	0.	0.	A7	16	QD8	0	T16	5	OP16	1111	1101

MODE	PART	RV	FV	FEED	DEPTH		MATERIAL	V%
BAR	OUT	230	300	0.48	1.	1	CBN-STL	0
	IN	0	0	0.	0.	2	ALY-STL	0
	FCE	0	0	0.	0.	3	CST-IRN	0
CPY	OUT	0	0	0.	6.3234	4	ALMINUM	0
	IN	0	0	0.	6.3236	5	STAINLS	0
	FCE	0	0	0.	6.528	6		0
CNR	OUT	0	0	*.****	6.528	7		0
	IN	0	0	0.	6.4808	8		0
	FCE	0	0	0.	6.528	9		0
EDG		130	200	0.42	0.5	10		0
THR		120	0	0.	0.	11		0
GRV		120	0	0.15	6.4641	12		0
DRL		20	0	0.25	0.	13		0
		0	0	0.	0.	14		0
		0	0	0.	0.	15		0
		0	0	0.	0.	16		0